

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEADQUARTERS: DELHI FIRE SERVICE: CANNAUGHT PLACE
NEW DELHI- 110 001

No. F.6/DFS/MS/School/2022/NDZ/ 652

Dated 21/10/2022

To,

The Principal,
MCD Nigam Pratibha Vidyalaya,
Krishna Nagar, Shahdara South,
Delhi- 110051

Sub:- Regarding Issuance Fire Safety Certificate r/o MCD Nigam Pratibha Vidyalaya located at Krishna Nagar, Shahdara South, Delhi- 110051.


Sir,

With reference to your email ID hos1051139@gmail.com dated 15/09/2022 on the subject cited above. In this connection, this is to inform you that the inspection of the above said premises was carried out by the officer concerned of this department in presence of HOS on dated 01/10/2022. During the inspection, it was observed that the shortcomings as communicated earlier vide letter No. F.6/DFS/MS/School/2022/174 dated 13/04/2022 (copy enclosed) have not been complied yet.

In view of the above, Fire Safety Certificate cannot be considered at this stage. You are once again suggested to rectify the said shortcomings under intimation to this office for further consideration in the matter.

Yours faithfully

Encl:- As above


(S. K. DUA)
DY. CHIEF FIRE OFFICER
o/c, DELHI FIRE SERVICE

Copy to:-

1. The Director of Education, MCD
15th Floor, E- Block, Dr. S.P. Mukherjee Civic Center, JLN Marg,
New Delhi-110002

C-36

**GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEADQUARTERS: DELHI FIRE SERVICE: CANNAUGHT PLACE
NEW DELHI- 110 001**

No. F.6/DFS/MS/School/2022/NDZ/ 174

Dated 13/4/2022

To,

The Principal,
EDMC Nigam Pratibha Vidyalaya,
Krishna Nagar, Shahdara South,
Delhi- 110051

Sub:- Regarding Issuance Fire Safety Certificate r/o EDMC Nigam Pratibha Vidyalaya located at Krishna Nagar, Shahdara South, Delhi- 110051.

Sir,

This is in reference to your letter No. nil dated 09/03/2022 on the subject cited above. In this connection, it is to inform you that the officer concerned of this department has carried out the inspection of the above mentioned School from fire safety point of view in presence of Mr. Sukhdev Singh, Teacher of the School. The following points / shortcomings were noticed in the building which is comprised of ground plus three upper floors.

1. First-Aid hose reels not provided.
2. Fire pump having 450 LPM output with 40 meter head not provided on terrace.
3. Exit signs are required to be provided in the school building at all exits.

In view of above, the building can not be considered for grant of fire safety certificate at this stage. Therefore you are suggested to rectify the above mentioned shortcomings under the intimation to this department for further course of action.

Yours faithfully

(Atul Garg)
Director

Delhi Fire Service

o/c

2.

Copy to:-

The Director of Education, EDMC
Udyog Sadan, Plot No. 419, FIE,
Patparganj, Delhi 92