GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEAD QUARTERS: DELHI FIRE SERVICE SEVEDE 1111 1 1000

No. F6/DFS/MS/School/2022/653

Dated 21 / 10/2022

To,

The Principal Govt. Sarvodaya Kanya Vidyalaya Vijay Nagar, Delhi-110042.

Sub:- Regarding issuance of fire safety certificate in r/o Govt. Sarvodaya Kanya Vidyalaya located at Vijay Nagar, Delhi-110042.

This has reference to your letter received through online e-mail dated 07.09.2022 on the subject cited above. In this connection this is to inform you that the above mentioned site was visited by the officer concerned of this department on 10.10.2022 in presence of Sh. Manoj Kumar (Estate Manager) to verify the compliance of the shortcomings/ observations already communicated by this department vide letter of even no. 341 dated 23.06.2022 and observed that the shortcomings have not been removed so far.

Keeping in view of above, Fire Safety Certificate cannot be considered at this stage.

Yours faithfully.

(Dharampal Bhardwaj) Dy. Chief Fire Officer Ph. No. 011-23414250

Copy to:-

1. The Director, Education, Government of N.C.T of Delhi. Old Sectt. Delhi – 110054.

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: NEW DELHI-110001

No. F-6/DFS/MS/School/2022/341

Dated 33/06/2022

To

The Principal Govt. Sarvodaya Kanya Vidyalaya Vijay Nagar, Delhi-110042.

Sub: - Regarding issuance of fire safety certificate in r/o Govt. Sarvodaya Kanya Vidyalaya (School Id No. 1309167) located at Vijay Nagar, Delhi-110042.

Sir,

Please refer to your letter received through email I.D dated 28.04.2022 on the subject cited above. In this connection this is to inform you that the above mentioned site was visited by the officer concerned of this department on 28.05.2022 to verify the fire safety measures issued vide NBC Part 4 and observed that the school premise is comprised of Single block, ground and 03 upper floors. At the time of inspection Smt. Alka Rani, Principal was also present at site. During the course of inspection observations/ shortcomings made are as under:-

- 1. Fire extinguisher provided in the building were checked and found short in no total 8nos ABC type required for school building.
- 2. Hose reel hose provided but found not functional at the time of inspection.
- 3. Hydrant provided but found not functional and some hoses found missing.
- 4. Terrace level fire fighting pump capacity of 450lpm but found not functional.
- 5. Terrace level fire water tank capacity of 10,000ltrs provided and found empty.

6. Exit signage found removed at some places.

Yours faithfully

(Dharampal Bhardwaj) Dy.Chief Fire Officer Ph:-011-23414250

Copy to: -

1. The Director of Education, Government of N.C.T of Delhi. Old Sectt. Delhi.