

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEADQUARTERS: DELHI FIRE SERVICE, NEW DELHI-110001

No. F.6/DFS/MS/NDZ/2022/ 2678

Dated: 25/10/2022

To

The Authorized Signatory,
NCDC Cell, Plot No.-22,
Sham Nath Marg, Civil Lines, Delhi.
Email ID- ncdccell001@gmail.com

Sub: Regarding renewal of Fire Safety Certificate (FSC) in r/o **M/s Dry Lab Block, NCDC, Complex (A Block), Plot No. 22, Sham Nath Marg, Civil Lines, Delhi.**


Sir,

This is in reference to email dated 22.09.2022 on the subject cited above. In this connection, it is to inform you that the above mentioned premise was visited by the officer concerned of this department on dated 06.10.2022 and observed that the shortcomings intimated vide letter of even No.F6/DFS/MS/NDZ/2020/628 dated 27/02/2020 (copy enclosed) have not been complied yet.

In view of above shortcomings, the application for issuance Fire Safety Certificate is rejected. The occupancy of the building/premises in absence of requisite fire safety arrangements shall be at the risk and liability of the owner/occupier. The Licensing authority/ Statutory Authority may take suitable necessary action as deemed fit.

Yours faithfully,

Encl: As above.


(S. K. Dua)

Dy. Chief Fire Officer
Delhi Fire Service
Tel. No:-011-23412222

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEADQUARTERS: DELHI FIRE SERVICE: NEW DELHI- 110001

No.F6/DFS/MS/NDZ/2020 / 698

Dated: 27/02/2020

To,

Dr. Smita Dhawan (Sr. CMO),
National Centre for Disease Control,
Directorate General of Health Services,
22- Sham Nath Marg, Delhi

Sub: - Regarding renewal of "Fire Safety Certificate" in r/o Dry Lab Block, NCDC, Complex (A Block), Plot No.22 Sham Nath Marg, Civil Lines, Delhi

Madam,

This has reference to letter no. nil dated 07.01.2020 on the subject cited above. In this connection above said building was inspected by officer concerned of this department on 03.02.2020 in the presence of Mr. Sunil Kumar Assistant and it was observed that the building comprised of ground + 05 upper floors and have following shortcomings were observed:-

1. First Aid Hose reels are found provided but not functional.
2. MOEFA was found provided but not functional.
3. Smoke detector was found provided but not functional.
4. Internal hydrant & yard hydrant found provided but not functional.
5. Main fire pump, Jockey pump and stand by pump found provided but not functional.
6. Detector panel system was not functional in fire control room.

In view of above, the fire safety certificate cannot be issued. You are suggested to rectify the above said shortcoming under the intimation to this department within 60days failing which action as per DFS Act will be initiated.

Yours faithfully,


(Atul Garg)
Director

Delhi Fire Service
Tel:-011-23414000

o/c RA.

Copy to:-

The Executive Engineer (Bldg.) H.Q.
North DMC, 8th floor, Civic Centre, Minto Road, New Delhi