<u>GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI</u> <u>HEAD QUARTERS : DELHI FIRE SERVICE : NEW DELHI – 110001</u>

No.F6/DFS/MS/NDZ/2022/GH 941

Dated: - 0.3. / .1. J. . / 2022

То

The Manager M/S Ashoka Palace, 8382-8383 & 8384, Arakashan Road, Pahar Ganj, New Delhi.

Sub: Regarding issuance of FSC in r/o M/S Ashoka Palace located at 8382-8383 & 8384, Arakashan Road, Pahar Ganj, New Delhi.

Sir,

This has reference to Online id no. 2022071814830 dated 10/08/22, on the subject cited above. In this connection, it is to inform you that the site was inspected by the officer concerned of this department on 26/10/2022 in the presence of **Manager** and following shortcomings were observed:-

- 1. Fire check doors are not provided
- 2. Smoke management system not provided as per gazette notification dated 27.05.2019.
- 3. Hose reel not functional at each floor.
- 4. CO detectors are not installed at corridors.
- 5. Fire Pump found non functional.

In view of above, Fire Safety Certificate cannot be issued. Therefore, you are requested to rectify the shortcomings for further consideration in the matter.

Yours faithfully,

(S.K. Dua) Dy. Chief Fire Officer Delhi Fire Service

Copy to:-

1. The Addl. Commissioner of Police (Lic.), Licensing Unit, Defense Colony Police Station, New Delhi.