GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELLA HEADQUARTERS: DELHI FIRE SERVICE, NEW DELHI-110001

No. F6/DFS/MS/School/WZ/2022/ 894

Dated: 14/11/2022

To.

The Principal, M. C. Primary School, Sector-18 B (New) at Rohini, Sector-18 Delhi-110089,

Sub:Issue of FSC in r/o M. C. Primary School, Sector-18 B (New) at Rohini, Sector-18 Delhi 110089. (School ID-1354538). Sir.

Kindly reference to online e-mail dated 21.09.2022, received in this department on the subject cited above. The premise was inspected by the concern nominated authority of this department on **02.11.2022**, in presence of **Mis. Poonam (School in-Charge)** to asceptain the availability and operability of the fire prevention and fire safety measures. The following shortcomings were observed:

- 1. Accessible gate width of 4.0 mtr against the required width of gate 4.5m.
- 2. Dead end travel distance from an exit is more than half of travel distance. i.e 15 motors.
- 3. Hall is having exit width of 1.4mrt instead of 2.0mtr
- 4. First Aid hose reel not provided.
- 5. Over Head water captive tank of 10,000 ltrs not provided.
- 6. Terrace Fire pump with capacity 450 LPM not provided.
- 7. The required exit signage are not provided.

In this regard as stipulated in sub Rule (5) of Rule 35 of DFS Act-2007 & Rule, 2010 it i. advised the applicant to apply with a fresh application for grant of fire safety certificate under sub-rule (2) on Form "I" and it shall be accompanied with a certificate from the architect and owner or occupier that all the fire prevention and fire safety measures are duly complying with the requirements as communicated under sub-rule (4) above, for further consideration in this regard. The web links for DFS Act-2007/ Rules 2010 & Form "I" are as under:

http://www.delhi.gov.in/wps/wcm/connect/doit_fire/FIRE/Home/Fire+Safety+Acts+....d+R_lles/ http://www.delhi.gov.in/wps/wcm/connect/doit_fire/FIRE/Home/Forms

Yours faithfully

Mc

Ph; 011-23414000