

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEADQUARTERS, DELHI FIRE SERVICE, NEW DELHI - 110001

No. F6/DFS/MS/2022/SZ/ 2971

Dated: 24/11/2022

To,

✓ The Dy. Commissioner of Police,
Dwarka Distt: Delhi,
Sector – 19, Dwarka, New Delhi

Subject: Regarding complaint of Shayshi K Bhalla in r/o Sri Agrasen CGSH Ltd. Located at Plot no-10, Sector-7, Dwarka, Phase – 1, New Delhi-110075.

Sir,

Please refer to your office letter No. 5582/HAC-III/DWD dated 21/10/2022 on the subject mentioned above. In this connection it is to inform you that the premises has already been inspected by the officer concern of this department and the shortcomings noticed has also been communicated vide this office letter No. F.6/DFS/MS/CGHS/SZ/2022/357, dated 14/02/2022 to the society management.

Enclose: - As above

Yours faithfully,



(Sunil Chaudhary)
Dy. Chief Fire Officer,
Delhi Fire Service.

Copy to: -

1. The Joint Director, DDA, Vikas Sadan, INA, New Delhi.
2. Ms. Shayshi K Bhalla, Sri Agrasen CGSH Ltd. Located at Plot no-10, Sector-7, Dwarka, Phase – 1, New Delhi-110075 <shayshi@gmail.com>

C 184 C 117

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEADQUARTERS: DELHI FIRE SERVICE: CONNAUGHT PLACE
NEW DELHI - 110001

NO. F6/DFS/MS/CGHS/SZ/2022/ 357

DATED: 14/02/2022

The President / Secretary
Sri Agrasen CGSH Ltd.
Plot no-10, Sector-7,
Dwarka, Phase - 1, New Delhi-110075

(PGMS ID- 2022000355)

Subject: - Complaint of fire fighting equipments in r/o Sri Agrasen CGSH Ltd. Located at Plot no-10, Sector-7, Dwarka, Phase - 1, New Delhi-110075.

Sir,

Please refer to complaint ID 2022000355 Dated-02/01/2022 on the subject cited above. In this connection it is to inform to you that the above said residential building has been inspected by the officer concerned of this department on 31/01/2022 for fire safety point of view.

During the course of inspection following shortcoming have been observed:-

1. Trimming of trees must be done to ensure free movement of fire vehicles around the building.
2. Staircases must be kept free from any obstruction & must not be locked at terrace.
3. Two fire extinguishers of ABC type 4 kg capacity must be provided and maintained at each floor in all blocks.
4. Hose Reels & Hydrants system found nonfunctional.
5. Two hoses with branch must be provided at each floor.
6. Manual call point found nonfunctional.
7. Terrace Pumps found nonfunctional.
8. Communication system in the lift found nonfunctional.

You are requested to comply the abovementioned shortcomings under intimation to this department.

The FSC issued vide letter no F6/DFS/MS/CGHS/2017/SZ/936 dated 29/06/2017 shall be remain suspended till the compliance of above shortcoming.

In view of the above shortcomings Fire Safety Certificate cannot be considered at this stage.

Yours faithfully,

(Ajay Garg)
(Director)

Delhi Fire Service

Copy to:-

1. The Joint Director, DDA, Vikas Sadan, INA, New Delhi.
2. Sh. Rakesh Bhardwaj Sri Agrasen CGSH Ltd. Plot no-10, Sector-7, Dwarka, Phase - 1, New Delhi-110075 Through PGMS