

1-69



GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI **HEADQUARTERS: DELHI FIRE SERVICE, NEW DELHI-110001**

No.F6/DFS/MS/NDZ/2022/NDZ/ School / 716 Dated: 23 /11 /2022

To

The Principal, Rajkiya Sarvodaya Bal Vidyalaya, Block-27, Trilokpuri, Delhi-110091.

Sub.:- Regarding renewal of Fire Safety Certificate in r/o Rajkiya Sarvodaya Bal Vidyalaya, Block-27, Trilokpuri, Delhi-110091.

Sir,

Please refer to your letter No. 355 dated 19/09/2022 on the subject cited above. In this connection, it is to inform you that the management has still not complied the office letter issued by this department vide letter no. F6/DFS/MS/2019/606 dated 31/01/2019 (copy enclosed).

In view of above, the application for issuance of Fire Safety Certificate is rejected. The occupancy of the building / premises in absence of requisite fire safety arrangements shall be at the risk and liability of the owner / occupier.

Yours faithfully,

Encl: as above

DY. CHIEF FIRE OFFICER

DELHI FIRE SERVICE.

Copy to:-

1. The Dy. Director of Education D-Block, Anand Vihar, Delhi.

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: CANNAUGHT PLACE NEW DELHI- 110001

NO. F6/DYS/MS/2019/606 To.

Dated: 31 / (| 19

The Principal.

Rajkiya Sarvodaya Kanya Vidyalaya,

Block-27, Trilokpuri, Delhi-91.

Sub: - Regarding issue of "Fire Safety Certificate" from fire safety point of view in r/o Rajkiya Sarvodaya Kanya Vidyalaya, Block-27, Trilokpuri, Delhi-

Madam.

Please refer to your letter RSKV/698 Dated 05/12/18 on the subject cited above. In this connection this is to inform you that officer concerned of this department inspected the school to verify the fire safety arrangements in accordance with the Circular no. F.16/Estate/CC/FS/2011/3298 to 3398 dated-1.3.11. At the time of inspection Mrs. Manju Khati (Principal) & Dilip Bist (Estate Manager) was present and it was observed that the school building is comprised of A & B block ground plus two upper and C & Primary blocks ground plus one upper floor and have following shortcomings:-

- 1. An additional staircase having width of 1.5 m shall be required in A, B &C block.
- 2. First Aid Hose reels not provided A & B block.
- 3. Fire pump having 450 LPM output at 40 m head not provided in A & B block at terrace.
- 4. Over head tank capacity of 10,000 liters not provided in A & B block.
- 5. Exit signage's not provided.

In view of above, the fire safety certificate cannot be considered at this stage. You are requested to rectify the above shortcoming under the intimation to this department for further course of action.

Yours faithfully

(Vipin Kental) Chief Fire Officer

· To.

The Principal, Rajkiya Sarvodaya Bal Vidyalaya, Block- 27, Trilokpuri, Delhi-91.

Copy to:-

1. The Dy.Director of Education, D-Block, Anand Vihar, Delhi