



GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE, NEW DELHI-110001

No. F6/DFS/MS/2022/NDZ/ 749

Dated: /9/ /2_/2022

To

The Principal, Bharti Public School, New Kondali, Mayur Vihar-III, Delhi-110096.

Sub.:- Inspection Report in r/o Bharti Public School, New Kondali, Mayur Vihar-III, Delhi-1100963.

Sir,

With reference to your letter No. BPS/MV/2022-23/2877 Dated 09/11/2022 & outdoor diary no. 7924 dated 11/11/2022 on the subject noted above. In this connection, it is to inform you that the said building premises was inspected by the officer concerned of this department on 05.12.2022 in the presence of Smt.Shalini Sabarwal (Principal).

During the course of inspection, it was observed that the building premises is comprised of Ground, 1st Floor, 2nd Floor & 3rd Floor only.

However following shortcomings were observed during the time of inspection:-

- 1. Few of the Fire Extinguishers Found empty.
- 2. First Aid hose Reel and Internal Hydrant found leaking.
- 3. Fire pump not on auto mode.
- 4. Exit signage found removed at some places.
- 5. No trained staff for operation of Fire Extinguishers/ Hose Reel Hose available.

In view of above shortcomings, the application for issuance Fire Safety Certificate is rejected. The occupancy of the building / premises in absence of requisite fire safety arrangements shall be at the risk and liability of the owner / occupier.

Yours faithfully,

(S.K. DUA)
Dy. CHIEF FIRE OFFICER
DELHI FIRE SERVICE.

Copy to:-

1. Director of Education, Old Secretariat, Civil Lines, Delhi-110054.