C34

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI **HEAD QUARTERS : DELHI FIRE SERVICE : NEW DELHI – 110001**

No.F6/DFS/MS/NDZ/2021/58/

Dated 21./.12/2021

To,

The Manager, Ignis Restaurant, B-45, 1st floor, Connaught Place, New Delhi – 110001.

Sub: Regarding renewal of FSC in r/o Ignis Restaurant (P.S. Enterprises) at B-45, 1st floor, Connaught Place, New Delhi. ID No. 2021112026863 dated 23.11.2021

Sir,

This has reference to your e-mail < aloklittle2@gmail.com dated 23.11.2021 & ID no. 2021112026863 dated 23.11.2021 on the subject cited above. In this regard, it is to inform you that the site was inspected by the officers concerned department on 15/12/2021 in the presence of Mr. Ajit Dubey and the following shortcomings were observed:-

- 1. Rear side staircase found locked.
- 2. Fire Extinguishers are due for refiling.
- 3. Hose reel, MOEFA, Sprinklers and fire pump found not functional.
- 4. Exit signage found inadequate.
- 5. Plastic sheet required to be removed wherever is used.

In view of above, the Fire Safety Certificate (FSC) cannot be issued. Therefore, you are requested to rectify the above shortcomings and re-submit for further consideration in the matter.

Yours faithfully,

(Dr. S.K.Tomar) Dy. Chief Fire Officer Delhi Fire Service

Copy to:-

1. The Addl. Commissioner of Police (Lic.), Licensing Unit, Defence Colony Police Station, New Delhi.