

257
C-37

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEADQUARTERS: DELHI FIRE SERVICE, NEW DELHI - 110001

No.F6/DFS/MS/School/NDZ/2021/ 01

Dated: 03/01/2022

To

Sunita Sharma,
HOS/ Vice Principal,
Indraprastha Hindu Girls Sr. Sec. School,
Jama Masjid, Delhi - 06.

Ref: Letter no. I.P/ Jama Masjid/1444 dated 24.12.2021.

Sub: Regarding grant of FSC.

Madam,

With reference to your letter mentioned above, it is informed that Delhi Fire Service is an executive body which functions under the ambit of Delhi Fire Service Act 2007 and Rules 2010. Relaxation in the existing fire safety norms/ law or providing alternatives to these norms is beyond the powers of this department. There are no alternatives/ options to the fire safety arrangements mentioned in your above referred letter. You are therefore requested to provide the required fire and life safety provisions as mentioned in the shortcomings letter no. F6/DFS/MS/EH/2019/NDZ/SCHOOL/4504 dated 25.07.2019 to ensure fire safety of the occupants and further consideration of Fire Safety Certificate.


Yours faithfully


31/12/21

(Dr. S. K. Tomar)

Dy. Chief Fire Officer

Tel: 011- 23412025

c/c 
31/12/21

Copy to :

The Directorate of Education,
Old Secretariat, Civil Lines.
Delhi - 06.

C-34

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEAD QUARTERS : DELHI FIRE SERVICE : NEW DELHI – 110001

No.F6/DFS/MS/EH/2019/NDZ/ *School 4504*

Dated

25/07/19

To,

The Vice Principal,
M/s Indraprastha Hindu Girls Sr. Sec. School,
Indraprastha Vidyalaya Marg,
Behind Jama Masjid, Delhi – 110006

Sub:- Regarding grant of FSC in r/o M/s Indraprastha Hindu Girls Sr. Sec. School,
Indraprastha Vidyalaya Marg, Behind Jama Masjid, Delhi – 110006

Sir,

This has reference to your letter No. IP/2019/770 dated 14/05/19 on the subject cited above, it is to inform you that the site was inspected by the officer concerned of this department on 10/07/2019 in the presence of Peon & Chowkidar and the following shortcomings were observed: -

1. First Aid hose reel not provided.
2. Automatic Sprinkler System in basement not provided.
3. Fire Pump capacity of 450 LPM is not provided.
4. Overhead water tank capacity of 15,000 Liters is not provided.
5. Exit signage not provided.

Hence, Fire Safety Certificate can not be considered at this stage.

Yours faithfully



(Sunil Chawdhary)
Dy. Chief Fire Officer
Delhi Fire Service

Copy to:-

The Director of Education,
Old Secretariat, Civil Lines,
Delhi-110054

9c 50