

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: NEW DELHI–110001

No. F.6/DFS/MS/School/2022/SZ/ 26

Dated: 27/ 0 /2022

C-9

То

The Principal, SDMC Primary Girls School, J.J Colony phase-I, Madanpur Kadar, New Delhi 110076.

Sub: Regarding issuance of Fire Safety Certificate (FSC) in r/o SDMC Primary Girls School, at J.J Colony phase-I, Madanpur Kadar, New Delhi 110076.

Sir,

This is in reference to with Gmail dated 09/12/2021 on the subject cited above. In this connection, it is to inform you that the above mentioned premise was visited by the officer concerned of this department and observed that the shortcoming intimated vide letter of even no. 4588 dated 13/12/2012 has yet not been complied. (Copy Enclosed for ready reference).

In view of above Shortcomings, the application for issuance Fire Safety Certificate is rejected. The occupancy of the building/premises in absence of requisite fire safety arrangements shall be at the risk and liability of the owner/occupier. The Licensing authority/ Statutory Authority may take suitable necessary action as deemed fit.

Yours faithfully,

(SUNIL CHAWDHARY) DY. CHIEF FIRE OFFICER (SZ)

Copy to

2. The Director of Education, South MCD, Civic Centre, Minto Road, New Delhi 110002

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEAD QUARTERS: DELHI FIRE SERVICE: NEW DELHI - 110001

No. F.6/DFS/MS/School/ 2012/4588

Dated 13/12/12

То

The Principal, M.C. Primary Boys School, JJ Colony Phase-1, Madanpur Khadar, New Delhi-110076

Sub: - Reg. grant of Fire N.O.C. in respect of M.C. Primary Boys School, JJ Colony Phase-1, Madanpur Khadar, New Delhi.

Sir,

This has reference to your letter no. Nil dated. 28/09/2012 on the subject cited above. In this connection the inspection of the said premises was carried out by the officer concerned of this department on 29/11/2012 to verify the fire safety arrangements provided in accordance with Directorate of Education Circular No. F.16/Estate/CC/Fire Safety/2011/3298-3398 dated 01/03/2011.During the visit, it was observed that the school building is comprised of ground floor only.

During the course of inspection, the following short-comings were observed: -

- 1. Class rooms with more than 45 students have only one exit, where as there should be two exits in each such class rooms having width of 1.0 mtrs.
- 2. Only 02 fire extinguishers found provided, which are inadequate. 02 more fire extinguishers to be provided.

In view of the above shortcomings, grant of Fire Safety Certificate / N.O.C. from fire safety point of view to the said premises can not be considered at this stage. You are requested to rectify the above mentioned shortcomings under intimation to this department.

Yours faithfully,

Dy. Chief Fire Delhi Fire Service

Copy to: -

1. Directorate of Education, Govt. of NCT of Delhi, Old Secretariat, Delhi.

south MCD Civic Centre