

299

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEAD QUARTERS: DELHI FIRE SERVICE : NEW DELHI – 110001

No. F6/DFS/MS/School/2022/35

Dated 27/01/2022

To,

The Principal
St.Mother Teresa Public School,
25 Ft Road, B-Block, Baba Colony,
Sant Nagar, Burari, Delhi-84


Sub: - Regarding issuance of fire safety certificate in r/o St. Mother Teresa Public School, 25 Ft Road, B-Block, Baba Colony, Sant Nagar, Burari, Delhi-84

Sir,

This has reference to your letter received through online E-Mail dated 17.12.2021 on the subject cited above. In this connection this is to inform you that the above mentioned site was visited by the officer concerned of this department on 31.12.2021 in presence of Sh. S. S Kaushal (Manager) and verify the compliance of the shortcomings/ observations already communicated by this department vide letter of even no. 355 dated 19.07.2021 and observed that the shortcomings have not been removed so far.

Keeping in view of above, Fire Safety Certificate cannot be considered at this stage.

Yours faithfully,


(Dharampal Bhardwaj)
Dy. Chief Fire Officer
Ph. No. 011-25156707

Copy to:-

1. The Director, Education, Government of N.C.T of Delhi. Old Sectt. Delhi – 110054.

o/e q

C-38

**GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEADQUARTERS: DELHI FIRE SERVICE: NEW DELHI-110001**

NO.F-6/DFS/HQ/ 2021/ 355

Dated 19/7/2021

To

The Manager
St.Mother Teresa Public School,
25 Ft Road, B-Block, Baba Colony,
Sant Nagar, Burari, Delhi-84

Sub: - St.Mother Teresa Public School, 25 Ft Road, B-Block, Baba Colony, Sant Nagar, Burari, Delhi-84.


Sir,

Please refer to your letter received through email I.D dated 15.06.2021 on the subject cited above. In this connection this is to inform you that the above mentioned site was visited by the officer concerned of this department on 29.06.2021 to verify the fire safety measures issued vide NBC Part- IV and observed that the school premise is comprised of ground and two upper floors. At the time of inspection Sh. S.S. Kaushal (Manager) was also present at site. During the course of inspection observations/ shortcomings made are as under:-

1. Fire extinguisher provided but not functional at the time of inspection.
2. First aid hose reel hose found removed at all floors.
3. MOEFA system not provided.
4. Terrace level fire fighting pumps capacity of 450 lpm found removed.
5. Terrace level water tank capacity of 10,000ltr found removed.
6. Exit signage and floor signage found removed at strategic locations in the building.
7. Electrical distribution panel are installed inside the stairwell, which need to be removed.

Keeping in view of above, fire safety certificate cannot be considered at this stage

Yours faithfully



(Dharampal Bhardwaj)
Dy. Chief Fire Officer
Ph:-011-25156707

Copy to:-

1. The Director, Education, Government of N.C.T of Delhi. Old Sectt. Delhi - 110054.