GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: CONNAUGHT PLACE NEW DELHI – 110001

NO. F6/DFS/MS/SZ/2022/ School 46

01 02 2022 DATED: () /01/2022

0-26

Smt. Sunita Nijhawan (Principal) <mcpsrajnagarextn1@gmail.com> S.D.M.C Primary Model School, Raj Nagar-Extension - II, Palam Colony, New Delhi – 110077.

Subject: Renewal of Fire Safety Certificate in r/o S.D.M.C Primary Model School, Located at Raj Nagar-Extension - II, Palam Colony, New Delhi - 110077.

Sir,

To,

Please refer to Email dated 29/12/2021 on the subject mentioned above. In this connection it is submitted that that the above said premises was visited by the officer concerned of this department on 06/01/2022 to see the compliance of the shortcomings communicated vide this office letter no. F.6/DFS/MS/SZ/2021/412 dated 13/08/2021 and found that the shortcomings are still not complied. You are requested to comply the shortcomings under intimation with this department.

In view of the above FSC from fire safety point of view cannot be considered at this stage.

Yours faithfully,

(Sunil Chaudhary) Dy. Chief Fire officer Delhi Fire Service

Copy to;-

1. Directorate of Education Old Secretariat Delhi - 110054

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: CONNAUGHT PLACE NEW DELHI – 110001

Dated: 13 /08/ 2021

G-2

No.F.6/DFS/MS/SZ/2021/4/2

To,

Smt. Sunita Nijhawan (Principal), S.D.M.C Primary Model School, Raj Nagar-Extension – II, Palam Colony, New Delhi – 110077.

Subject: Renewal of Fire Safety Certificate iro S.D.M.C Primary Model School, Located at Raj Nagar-Extension – II, Palam Colony, New Delhi – 110077.

Sir,

Please refer to your Email dated 14/07/2021 on the subject mentioned above. In this connection it is to inform you that the premises was inspected by the officer concerned from this department on 02/08/2021 for fire safety point of view.

The following shortcoming was observed during the time of inspection:-

- 1. Hose reel hose found non functional
- 2. Terrace pump found nonfunctional.
- 3. Over head water tank of 10,000 ltr capacity found empty.

You are requested to comply the above mentioned shortcomings under intimation to this department for further necessary action.

In view of the above shortcomings Fire Safety Certificate cannot be considered at this stage.

Yours faithfully,

(Sunil Chaudhary) Dy. Chief Fire Officer Delhi Fire Service.

Copy to; - Directorate of Education Old Secretariat Delhi - 110054