GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: NEW DELHI-110001

NO. F-6/DFS/MS/EH/SZ/2022/ 31

Dated:- 27/01/2022

To,

Sh. Dev Arora(Owner), M/s. UP UR Place A Unit of DA Restaurant Pvt. Ltd., located at 22-B, 3rd Floor, Bazar Marg, Old Rajendra Nagar, Pusa Road, New Delhi- 110060..

Sub: - <u>Regarding issuance of fire safety certificate in r/o M/s. UP UR Place A Unit of DA</u> <u>Restaurant Pvt. Ltd., located at 22-B, 3rd Floor, Bazar Marg, Old Rajendra Nagar, Pusa</u> <u>Road, New Delhi-110060.</u>

Sir,

Please refer to online application ID 2021122529332 dated 27.12.2021on the subject cited above. Above said eating house running at third floor of a building comprised of basement, stilt, ground plus three upper floors. In this connection it is to inform you that the above said assembly building (Restaurant) was inspected by the officer concerned of this department from safety point of view on 06.01.2022 in presence of Mr. Dev Arora, Owner of the restaurant.

During the course of inspection it has been observed that fire safety arrangements such as fire extinguishers found provided, However the following shortcomings have been observed:-

- 1 Two staircases having width of 1.35 mts. & 1.50 to 2.0 mts are provided against required width of 1.50 mts. each.
- 2 Exit door having width of 1.20 mts. & 1.44 mts. are provided against required width of 1.50 mts. each.
- 3 Fire Check Doors are not provided in kitchen.
- 4 Smoke ventilation not provided.
- 5 Smoke Detector found not provided.
- 6 MOEFA found not provided.
- 7 P.A system found not provided.
- 8 Internal hydrant system found not provided.
- 9 Required electrical fire pump capacity of 2280 LPM and standby diesel pump of 2280 LPM capacity along with jockey pump of 180 LPM are not provided.
- 10 Terrace pump capacity 450 LPM is not provided.
- 11 Underground water tank requirement of 1,00000 lts capacity found not provided.

12 Exit signages are not provided at the places mentioned during the inspection.

Keeping in view of above, fire safety certificate cannot be considered at this stage. You are requested to rectify the above said shortcomings for taking further necessary action in this matter.

Yours faithfully Director Ph: 011-23414000

Copy to:-

1. The Executive Engineer (Building), North MCD, Karol Bagh, Anand Parbat, New Delhi.