

C 9

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEADQUARTERS: DELHI FIRE SERVICE, NEW DELHI-110001

No.F6/DFS/MS/School/2022/SZ/ 61

Dated: 11/02/2022

To

Sh. Om Prakash Meena,
School Inspector (Gen),
Central Zone (SDMC),
Lajpat Nagar-II, New Delhi-110024.

Sub.:- Inspection Report of Sri Guru Nanak Khalsa Primary School, Kotla Mubarakpur, New Delhi-110003.

Sir,

Please refer to your letter No. D/DDE/CA/2022/4375 dated 05/01/2022 and outdoor diary No. 5708 dated 06/01/2022 on the subject cited above. In this connection it is to inform you that the premises was visited by officer of this deptt. on dated 18/01/2022 in presence of Sh. Manjeet Singh (Chairman) and observed that management has still not complied the office letter issued by this department vide letter No. F6/MS/DFS/School/2012/1045 dated 23/03/2012. (Copy Enclosed).

In view of above shortcomings, the application for issuance Fire Safety Certificate is rejected. The occupancy of the building / premises in absence of requisite fire safety arrangements shall be at the risk and liability of the owner / occupier. The Licensing Authority / Statutory Authority may take suitable necessary action as deemed fit.

Yours faithfully,



(SUNIL CHAWDHARY)
DY. CHIEF FIRE OFFICER (S.Z.).

o/c AS

Copy to:-

1. The Principal, Sri Guru Nanak Khalsa Primary School, Kotla Mubarakpur, New Delhi-03.

C-4

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEADQUARTERS, DELHI FIRE SERVICE, CONNAUGHT PLACE
NEW DELHI

No.F6/MS/DFS/School/2012/ 1045
To,

Dated: 23/03/12

The Principal,
Sri Guru Nanak Khalsa Primary School,
Kotla Mubarakpur, New Delhi-110003.

Sub:- Inspection report from fire safety point of view in r/o Sri Guru Nanak Khalsa
Primary School, Kotla Mubarakpur, New Delhi-110003.

Sir,

This has reference to your letter No. 1274/12 dated 17/01/12 on the subject cited above. In this connection the school premises have been visited by the officers concerned from this department to verify the compliance of fire safety measures required as per circular of Director of Education, Govt. of NCT of Delhi.

During inspection, it was observed that the premises in question are comprised of ground + 2 upper floor. There are shops at ground floor but the school is running on 1st & 2nd floor.


The following shortcomings were observed:-

1. Additional staircase required.
2. Every class room required two doors.
3. First-Aid hose reel not provided on each floor.
4. Over head water tank capacity 10,000 Ltrs capacity not provided.
5. Boosting arrangement for hose reel not provided.
6. Exit signage not provided at every location on each floor.
7. Fire extinguishers provided but not adequate.

In view of above shortcomings NOC from fire safety point of view to the said premises can not be considered at this stage.

You are requested to rectify the aforesaid shortcomings under intimation to this department.

Yours faithfully,



Chief Fire Officer
Delhi Fire Service

28
2