

**GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI**  
**HEADQUARTERS: DELHI FIRE SERVICE: NEW DELHI-110001**

No: F.6/DFS/MS/School/WZ/2022/ 87

Dated: - 25/02/2022

To,

The Principal,  
Gurusharan Convent School,  
GH-9, Paschim Vihar, New Delhi- 110087.

Sub.:- Regarding renewal of Fire Safety Certificate in r/o Gurusharan Convent School, GH-9, Paschim Vihar, New Delhi- 110087.

Sir,

Please refer to your letter No. GSC/2021-22/196 dated 04.01.2022 on the subject cited above. In this connection, it is to inform you that the aforesaid school building have been inspected by the officer concerned of this department in presence of Sh. Harpreet (caretaker) on 31.01.2022 to check the status of the shortcomings pointed out by this department vide letter No. F.6/DFS/MS/School/WZ/2021/683 dated 27.12.2021, but no improvement was observed during the course of inspection.

In view of above, the application for issuance of Fire Safety Certificate is not considered at this stage & rejected. The occupancy of the building/premises in absence of requisites fire safety measures shall be at the risk and liabilities of the owner/occupier.

Yours faithfully

(Dharampal Bhardwaj)  
Dy. Chief Fire Officer  
West Zone

Copy to: -

The Director of Education,  
Govt. of NCT of Delhi, Old Secretariat, Delhi.

-for information please

24/1/22  
17/2/22.

30

**GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI  
HEADQUARTERS: DELHI FIRE SERVICE: NEW DELHI-110001**

No: F.6/DFS/MS/School/WZ/2021/ 683

Dated: - 27/12/2021

To,

The Principal,  
Gurusharan Convent School,  
GH-9, Paschim Vihar, New Delhi- 110087.

Sub.: - Regarding renewal of Fire Safety Certificate in r/o Gurusharan Convent School, GH-9, Paschim Vihar, New Delhi- 110087.

Sir,

Please refer to your E-mail dated 24.11.2021 on the subject cited above. In this connection, it is to inform you that the aforesaid school building have been inspected by the officer concerned of this department in presence of Sh. Harpreet (Accountant) on 06.12.2021 to check the functionability of the existing fire safety arrangements in the school building.

During inspection, it has been observed that the said school building is comprised of basement, ground plus three upper floors. Fire safety arrangements such as fire extinguishers, exit signage, first aid hose reel, MOEFA, PA system, down comer, overhead water tank etc. found provided in the school building. However, the following shortcomings were observed:-

1. Use of basement floor as classroom, library etc. is not allowed.
2. Two terrace pumps capacity 450 LPM & 180 LPM are provided but not functional.
3. First aid hose reel is provided but not functional.
4. Down comer system is provided but not functional.
5. Automatic sprinkler system in basement floor is provided but not functional.
6. Smoke management system at basement floor found removed.

In view of above shortcomings, the application for issuance of Fire Safety Certificate is not considered at this stage & rejected. The occupancy of the building/premises in absence of requisites fire safety measures shall be at the risk and liabilities of the owner/occupier.

Yours faithfully

(Dharampal Bhardwaj)  
Dy. Chief Fire Officer  
West Zone

27/12/21  
22/12/21

Copy to: -

The Director of Education,  
Govt. of NCT of Delhi, Old Secretariat, Delhi.

-for information please