



C-37

7
Azadi Ka
Amrit Mahotsav

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEADQUARTERS: DELHI FIRE SERVICE, NEW DELHI-110001

No. F6/DFS/MS/2022/NDZ/ 755

Dated: 26/12/2022

To

The Principal,
Saraswati Public Secondary School,
Budh Vihar, Mandoli, Delhi-110093.

Sub.:- Inspection Report in r/o Saraswati Public Secondary School, Budh Vihar, Mandoli, Delhi-110093.

Sir,

With reference to your letter No. SPSS/2022-23/51 Dated 25/11/2022 on the subject noted above. In this connection it is to inform you that the said building premises was inspected by the officer concerned of this department on 17.12.2022 in the presence of Mrs. Santosh Aggarwal.

During the course of inspection it was observed that the building premises is comprised of Ground, 1st Floor & 2nd Floor only.

However following shortcomings were observed during the time of inspection:-

1. First Aid Hose Reel and Down Comer found removed.
2. Fire pump of 220LPM found removed.
3. Over Head tank capacity of 2,500 ltr found removed.
4. Exit signage found removed.

In view of above shortcomings, the application for issuance Fire Safety Certificate is rejected. The occupancy of the building / premises in absence of requisite fire safety arrangements shall be at the risk and liability of the owner / occupier.

Yours faithfully,


22/12/22

(S.K. DUA)

**DY. CHIEF FIRE OFFICER
DELHI FIRE SERVICE.**

Copy to :-

1. Director of Education, Old Secretariat, Civil Lines, Delhi-110054.

o/c 