



GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEADQUARTERS: DELHI FIRE SERVICE, NEW DELHI-110001

No. F6/DFS/MS/2022/NDZ/ 760

Dated: 28/12 /2022

To

The Principal,
Bal Bhavan Public School,
A-Block, Swasthya Vihar, Delhi-110092.

Sub.:- Inspection Report in r/o Bal Bhavan Public School, A-Block, Swasthya Vihar, Delhi-110092.

Sir,

With reference to your letter No BBPSSV/2022-23/344 dated 21/11/2022 on the subject noted above. In this connection, it is to inform you that the said building premises was inspected by the officer concerned of this department on 17.12.2022 in the presence of Smt. Rachna Gupta (Principal).

During the course of inspection it was observed that the building premises is comprised of Basement, Ground, 1st floor & 2nd floor only.

However following shortcomings were observed during the time of inspection:-

1. 02 staircase of width 1.50mtr & 1.20mtr provided against requirement of 2 staircase of width 1.50mtr each on upper floors.
2. Hose Reel Hose not provided on Ground Floor & 2nd Floor.
3. Automatic Sprinkler System in basement not provided.
4. Fire Pump of 450 Lit/min capacity provided against requirement of 900 Lit/min capacity.
5. Overhead tank capacity of 5,000 ltrs provided against requirement of 15,000 ltrs.
6. Exit Signage not provided.

In view of above shortcomings, the application for issuance Fire Safety Certificate is rejected. The occupancy of the building / premises in absence of requisite fire safety arrangements shall be at the risk and liability of the owner / occupier.

Yours faithfully,

(ATUL GARG)
DIRECTOR
DELHI FIRE SERVICE

Copy to :-

1. Director of Education, Old Secretariat, Civil Lines, Delhi-110054.