



GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEADQUARTERS: DELHI FIRE SERVICE: NEW DELHI- 110001

75
आजादी का
अमृत महोत्सव

No.F6/DFS/MS/School/SZ/2022/ 764

Dated: 28/12/2022

To

The Principal,
Shaheed Hemu Kalani Govt. Sarvodaya Bal Vidyalaya,
Ring Road, Lajpat Nagar-II,
New Delhi-110024.

Sub:- Regarding renewal of Fire Safety Certificate in r/o Shaheed Hemu Kalani Govt. Sarvodaya Bal Vidyalaya, Ring Road, Lajpat Nagar-II, New Delhi-110024.

Sir,

This has reference to your letter no. SHK/SBV/2022/365 dated 18.11.2022 on the subject cited above, it is informed that the said building was visited by Assistant Divisional Officer (M. Road) from this department in the presence of Mr. Satpal Sharma (Estate Manager) and it was observed that the shortcomings already communicated by this department vide letter no. F6/DFS/MS/School/2019/SZ/3552 dated 14.06.2019 (Photocopy enclosed) has not been completely rectified till date.

In view of above shortcomings, the application for issuance for Fire Safety Certificate is rejected. The occupancy of the building/premises in absence of requisite fire safety arrangements shall be at the risk and liability of the school management. The Statutory Authority may take suitable necessary action as deemed fit.

Yours faithfully,

(Sunil Chawdhary)
Dy. Chief Fire Officer
Delhi Fire Service

Copy to:-

1. The Directorate of Education, Govt. of NCT of Delhi, Old Secretariat, New Delhi.
2. The Dy. Director of Education, GNCT of New Delhi DISST. South Block-C, Defence Colony, New Delhi-24.

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEADQUARTERS: DELHI FIRE SERVICE: NEW DELHI- 110001

No. F.6/DFS/MS/School/2019/SZ/ 3552

Dated: .../.../2019

To

The HOS,
Shaheed Hemu Kalani,
Govt. Sarvodaya Bal Vidyalaya,
Ring Road, Lajpat Nagar-II, New Delhi-110024

Sub.:- Reg. Renewal of FSC.

Sir,

This is in reference with your letter No. SHK/SBI/2019/1308 Dated 19-02-2019 received through outdoor diary No.3620 dated 19/02/2019 on the subject cited above. In this connection, the school premise was re-visited by officer concern of this department on 27/05/2019 in the presence of Mr. N. K. Sharma (HOS) and observed that the department issued FSC vide letter no F6/DFS/MS/School/2015/SZ/1301 Dated 21/07/2015 for ground plus three upper floors. School management constructed new building- New Block- B & C wing G + 2 (A, B & C both blocks are interconnect), Primary Wing - G + 2 & G + 1 (both are interconnect), Audi Block- ground floor only To verify the status of fire prevention and fire safety measures already provided therein in your presence. During the inspection, the shortcomings observed are as below: -

1. One staircase with the width of 1.50m required in primary block for G +2 block.
2. First aid hose reel provided in old block found nonfunctional and not provided in b & c block, primary block and Audi block.
3. MOEFA not provided in Audi block.
4. Sprinkler system not provided in Audi.
5. Internal hydrant not provided in Audi block.
6. Terrace pump provided in old block with capacity of 450LPM with Head 40m found nonfunctional and not provided in b & c block, primary block and Audi block. With the capacity of 450 LPM and 40m head required at terrace on auto mode.
7. Overhead tank capacity of 10,000 liter found removed in old block and not provided at terrace of b & c block, primary block and overhead tank capacity of 5,000 liter not provided at terrace of Audi.
8. Exit sign not provided at each floor.

In view of above shortcomings, issuance of FSC cannot be considered at this stage. You are requested to rectify the shortcoming under intimation to this department for further consideration in the matter.

Yours faithfully,


Anil Garg
Chief Fire Officer
Tel. 011-23414250

Copy to: -

1. The Director of Education, Govt. of NCT of Delhi, Old Secretariat, New Delhi.