GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE, CONNAUGHT PLACE **NEW DELHI- 110001**

No. F6/DFS/MS/school/2022/SZ/ 761

Dated: 28/12/22

To,

The Manager, Vikas Valley Public School, S-11,12,13-S-Block, Vikas Nagar, Hastal, New Delhi.

Sub: - Regarding issuance of "Fire Safety Certificate" from fire safety point of view in r/o Vikas Valley Public School, S-11, 12, 13-S-Block, Vikas Nagar, Hastal, New Delhi.

Sir,

This has reference to your letter Nil dated 01/12/2022 on the subject captioned above. In this connection, it is to inform you that the above mentioned school building was inspected by the officers concerned of this department on 15/12/2022 in the presence of Sh. Sumil Arora (Principal) to verify the compliance of shortcoming already communicated by this department vide letter No.F6/DFS/MS/School/2022/SZ/267 dated 30/05/2022 and observed that Shortcomings are still not rectified. The management will be held responsible for any untoward incident for the period if compliance is not made.

Yours faithfully (SUNIL CHAWDHARY) DY.CHIEF FIRE OFFICER Lep,

Copy to:-

The Director of Education, Govt. Of NCT of Delhi, Old Secretariat, New Delhi-110054.

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: CANNAUGHT PLACE NEW DELHI- 110001

No. F6/DFS/MS/School/2022/SZ/ 267

Dated: 30/05/2022

To,

The Manager, Vikas Valley Public School, S-11,12,13-S-Block, Vikas Nagar, Hastal, New Delhi.

Sub: - Regarding issuance of "Fire Safety Certificate" from fire safety point of view in r/o Vikas Valley Public School,S-11,12,13-S-Block, Vikas Nagar,Hastal, New Delhi.

Sir,

Please refer to your letter no. VVPS/04/2022 Dated- 07/04/2022 on the subject cited above. In this connection this is to inform you that officer concerned of this department inspected the school building on 17/05/2022 to verify the fire safety arrangements in accordance with the rules. At the time of inspection Sh Sumil Arora (Principal) was present and it was observed that the school building is comprised of ground plus two upper floors and have following shortcomings.

- 1. One staircase shall be provided of 1.5 m wide.
- 2. An additional hose reel shall be provided.
- 3. Fire pump having 450 lpm provided but not functional.

In view of above shortcomings, the application for issuance Fire Safety Certificate is rejected. The occupancy of the building/premises in absence of requisite fire safety arrangements shall be at the risk & liability of the owner/occupier. The Licensing Authority/Statutory Authority may be take suitable necessary action as deemed fit.

Director Delhi Fire Service

Copy to: -.

1. The Director of Education, Govt of NCT of Delhi, Old Secretariat, New Delhi-110054. (with a request to take further action as school does not have fire NOC)