

## GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: NEW DELHI- 110001



No. F.6/DFS/MS/EH/WZ/2023/ 02

Dated: 02/01/2023

To.

The Joint Commissioner of Police, Licensing Unit, 1<sup>st</sup> Floor, Police Station Defence Colony, New Delhi.

Subject: Inspection report for issuance of Fire safety Certificate in r/o M/s. Tata Starbucks

Private Limited, Shop No. 1/83, GF, West Punjabi Bagh, Club Road, New Delhi –26.

Sir,

With reference to the online application received through MHA portal vide ID-2022102719440 on the subject cited above. In this connection, it is to inform you that the above said premises was inspected by the officer concerned of this department on 28.11.2022, to check the required fire safety arrangements as per laws in the building.

During the course of inspection, it was observed that the restaurant is running at ground floor having two exits in a building comprised of basement, ground plus three upper floors. Fire safety arrangements such as fire extinguisher, MOEFA, exit signages, first aid hose reel, internal hydrant etc. found provided. However, following shortcomings were observed: -

- 1. Overhead water tank capacity of 20,000 ltrs is not provided.
- 2. Terrace pump capacity 450 LPM is not provided.

In view of above Shortcomings, the application for issuance of Fire safety Certificate is not considered at this stage & rejected. The occupancy of the building/premises in absence of requisites fire safety arrangements shall be at the risk and liabilities of the Owner/occupier.

Yours Faithfully

(Atul Garg) Director

Copy To:-

- 1. The owner/occupier M/s Tata Starbucks Private Limited, Shop No. 1/83, GF, West Punjabi Bagh, Club Road, New Delhi –110026.
- 2. The Deputy Health Officer, West Zone, MCD, Rajouri Garden, New Delhi.