



GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEADQUARTERS: DELHI FIRE SERVICE: NEW DELHI- 110001



No.F6/DFS/MS/School/SZ/2023/29

Dated: 17/01/2023

To

The Principal,
G.B. Pant Govt. Sarvodaya Bal Vidyalaya,
Srinivaspuri New Delhi-110065.

Sub:- Regarding renewal of Fire Safety Certificate in r/o G.B. Pant Govt. Sarvodaya Bal Vidyalaya located at Srinivaspuri New Delhi-110065.

Sir,

This has reference to your email dated 20.12.2022 on the subject cited above, it is informed that the said building was visited by Assistant Divisional Officer (M. Road) from this department on 10.01.2023 in the presence of D.N. Jha (Estate Officer) and it was observed that the shortcomings already communicated by this department vide letter no. F6/DFS/MS/School/SZ/2022/262 dated 27.05.2022 (Photocopy enclosed) has not been completely rectified till date.

In view of above shortcomings, the application for issuance for Fire Safety Certificate is rejected. The occupancy of the building/premises in absence of requisite fire safety arrangements shall be at the risk and liability of the management. The Statutory Authority may take suitable necessary action as deemed fit.

Yours faithfully,

(Sunil Chawdhary)
Dy. Chief Fire Officer
Delhi Fire Service

17/01/23

Copy to:-

1. The Directorate of Education, Govt. of NCT of Delhi, Old Secretariat, Delhi.

4/16

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEADQUARTERS: DELHI FIRE SERVICE, NEW DELHI – 110001

No.F6/DFS/MS/School/SZ/2022/262

Dated: 27/05/2022

To

The Principal,
G.B. Pant Govt. Sarvodaya Bal Vidyalaya,
Srinivaspuri New Delhi-110065.

Sub:- Regarding renewal of Fire Safety Certificate in r/o **G.B. Pant Govt. Sarvodaya Bal Vidyalaya located at Srinivaspuri New Delhi-110065.**


Sir,

With reference to your letter no. GBP/SBV/SNP/2022-23/672 dated 21.04.2022 on the subject cited above, it is informed that the school building was inspected by Assistant Divisional Officer (M. Road) from this department on 05.05.2022 in the presence of Dr. Akhtar (HOS) and it was observed that the building is comprised of two blocks (Ground + 02 upper floors & Ground + 01 upper floors). During the inspection following shortcomings were observed:-

1. First-aid-hose reels found non function.
2. Fire pump found non functional.
3. Terrace tank having total capacity of 10,000 liters shall be provided exclusively for fire fighting.

In view of above shortcomings, the application for issuance for Fire Safety Certificate is rejected. The occupancy of the building/premises in absence of requisite fire safety arrangements shall be at the risk and liability of the school management. The Authority/Statutory Authority may take suitable necessary action as deemed fit.

Yours faithfully,


(Sunil Chawdhary)
Dy. Chief Fire Officer
Delhi Fire Service

mc 
27/5

Copy to:-

The Dy. Director of Education, GNCT of New Delhi DISST. South Block-C, Defence Colony, New Delhi-24.