



GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI  
HEADQUARTERS: DELHI FIRE SERVICE: NEW DELHI- 110001



No. F6/DFS/MS/2023/WZ/ 247  
To,

Dated:- 07/02/2023

The Authorized Signatory,  
M/s. Amit Polymers (India),  
J-31, Udyog Nagar, Rohtak Road  
New Delhi-110041.

**Subject: - Regarding issuance of Fire Safety Certificate in respect of M/s. Amit Polymers (India) Located at J-31, Udyog Nagar, Rohtak Road, New Delhi-110041.**

Sir,

Please refer to your letter no. nil dated nil on the subject cited above. In this connection it is to inform you that the said building have been inspected by the officer concerned of this department on 23.01.2023 in the presence of Sh. Jagdish to check compliance of shortcomings issued by this department vide letter no. F6/DFS/MS/2014/709 dated 13.03.2014 (Copy enclosed).

During inspection, it have been observed that the shortcomings issued by this department vide above said letter has not been rectified yet.

In view of the above shortcomings, Fire safety Certificate cannot be grant at this stage. You are advised to rectify the above mentioned shortcomings under intimation to this department for taking further necessary action.

Yours faithfully,

  
(Dharampal Bhardwaj)  
Dy. Chief Fire Officer  
(West Zone)

AC  
07/02/23

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI  
HEADQUARTERS: DELHI FIRE SERVICE, NEW DELHI-110001

p. F6/DFS/MS/2014/709

Dated: 13/03/2014

To

Amit Polymers (India),  
J-31, Udyog Nagar,  
Rohtak Road,  
New Delhi-110041.

Sub: - Issuance of Fire Safety Certificate in respect of Amit Polymers (India),  
J-31, Udyog Nagar, Rohtak Road, New Delhi-110041 from fire safety point of view.

Sir,

Please refer to your letter No. Nil dated Nil on the subject noted above, it is to inform you that the said building premises was inspected by the officer concerned of this department on 13/02/2014 in the presence of Sh. Jagdish and observed that the factory is constructed on a plot area measuring about 804m<sup>2</sup> comprising Basement, G.F., Mez. F. and 1<sup>st</sup> Floor. The area of the basement is 401m<sup>2</sup> (approx.). The applicant has provided Fire Safety arrangements such as Fire Extinguishers, Hose Reel Hose etc.

However following shortcomings were observed during the time of inspection:-




1. Self-closing fire check door is not provided in the basement.
2. First aid hose reel provided but found nonfunctional.
3. Over Head Tank of capacity 2,000 lts. found removed.
4. Fire Pumps not provided.

The Building premises is not meeting the Fire Safety Guidelines issued by this deptt. vide letter No. F6/DFS/MS/BP/85/707 dated 06/08/1985.

Keeping in view of above, fire safety certificate cannot be recommended at this stage.

Further, The Fire Safety Certificate issued by this deptt. vide letter No. F6/DFS/MS/89/BP/842 dated 16/05/1989 is suspended until rectification of above quoted shortcomings.

Yours faithfully

  
(Vipin Kental)  
Dy. Chief Fire Officer  
Delhi Fire Service  
Phone:-23846352  
E-mail: dcfowz.dlfire@nic.in.  
 

Copy to:-

1. The Commissioner, North Delhi, Municipal Committee, Civic Center, J.L. Nehru Road, New Delhi-110002, for taking necessary action as deemed fit.