



GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEADQUARTERS: DELHI FIRE SERVICE: NEW DELHI- 110001



No. F6 /DFS/MS/Industrial/SZ/2023/69

Dated: 24/03/2023

To,

The Executive Engineer (Bldg.) HQ,
South Delhi Municipal Corporation,
9th Floor, Civic Centre, Minto Road,
New Delhi – 110002.

Ref:- JSI Request ID – 10112375, MCD portal

Sub:- Joint Site Inspection in r/o M/s M/s Hamdard Laboratories (India), Building Block – A,
Plot No. B-317 & 318, , Okhla Industrial Area, Phase-I, New Delhi-20.

Sir,

This has reference to the online application for JSI mentioned above In this context it is informed that the said building block was inspected by a team of officers concerned of this department on 21.03.2023 in the presence of Mr. Ali Javed (AGM, project), Md. Mubin (Sr. Manager, Project), Sh. M. S. Meena (A. E. Bldg.) and Sh. Bhagat Dayal (J.E. Bldg.) in a joint site inspection of Delhi Fire service and MCD and it was observed that the building **Block- A** is comprised of **Basement + Ground + 1 upper floor**. During the inspection following shortcomings were observed:

1. Horizontal & vertical opening is not sealed.
2. Water curtains found not provided in Car lift
3. Main Fire pump was not in auto mode and pump not delivering required pressure on terrace.
4. Lift lobby not provided at some floors.
5. Pressurization system or Natural ventilation not provided in Staircase.
6. Pressurization of Lift well/ Lift Lobby not provided.
7. Exit & Lift signages found not provided.

In view of above shortcomings, the online application for issuance for Fire Safety Certificate is rejected. The occupancy of the building/premises in absence of requisite fire safety arrangements shall be at the risk and liability of the management. The Authority/Statutory Authority may take suitable necessary action as deemed fit.

Yours faithfully,

(Atul Garg)
Director

Delhi Fire Service

22/3/23