



No. F6 /DFS/MS/Industrial/SZ/2023/1342

Dated: 03/07/2023

To,

The Authorized Signatory,
Plot no. A-27, MCIE,
Mathura Road, New Delhi-44.

Sub: - Regarding renewal of Fire Safety Certificate in r/o M/s Plot no. A-27, MCIE, Mathura Road, New Delhi-44.

Sir,

This has reference to the outdoor diary no. 2594 dated 07.06.2023 on the subject cited above, it is informed that the said building was inspected by a team of officers concerned of this department on 22.06.2023 in the presence of Mr. R.P. Singh (Manager) and it was observed that the building is comprised of two blocks (each block having Ground + 02 upper floors). During the inspection following shortcomings were observed:

1. Fire check door (FCD's) found removed at some floors in 2nd block.
2. Automated security system in Fire check door (FCD's) of staircases not synchronized with ADAS/MOEFA.
3. Ventilation provisions are not adequate in 2nd block.
4. Loft portion of Tata showroom shall be provided with in two exits/staircases.
5. Some of the doorways in 2nd block are not meeting the required exit width.
6. Hose reels, Internal & Yard hydrant found non functional due to heavy leakage in hydrant lines in 1st block.
7. Fire pumps were not in auto mode.

In view of above shortcomings, the application for issuance for Fire Safety Certificate is rejected. The occupancy of the building/premises in absence of requisite fire safety arrangements shall be at the risk and liability of the management. The Authority/Statutory Authority may take suitable necessary action as deemed fit.

Yours faithfully,

(Aul Garg)

Director

Delhi Fire Service

03/07/23 MGA

Copy to:-

1. The Executive Engineer (Building), South DMC, Jal Vihar, Lajpat Nagar, New Delhi-24.