

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI  
HEADQUARTERS: DELHI FIRE SERVICE: NEW DELHI- 110001

No. F6/DFS/MS/2023/WZ/college/32

Dated:- 06/07/2023

To,

The Authorized Signatory,  
Frankfinn Aviation Service Pvt. Ltd.,  
A-16, Vishal Enclave, Near Oriental Bank,  
New Delhi-110027..

**Subj:- Regarding renewal of Fire Safety Certificate in respect of Frankfinn Aviation Service Pvt. Ltd., located at A-16, Vishal Enclave, Near Oriental Bank, New Delhi-110027.**

Sir,

This has reference to your letter no nil dated nil on the subject cited above. In this connection, it is to inform you that the said building was inspected by the officer concerned of this department on 29.06.2023 in the presence of Sh. Rahul Kamboj (Manager).

During the inspection, it was observed that the building is comprised of Stilt + Ground + 03 Upper Floors. Fire Safety arrangements such as fire extinguishers, first aid hose reel, & Overhead water storage tank etc found provided. However, the following points have been noticed as shortcomings:-

1. The width of Corridor at 3<sup>rd</sup> floor found reduced to 1.0 m against required of 1.5 m.
2. First aid hose reel found non-functional & at 2<sup>nd</sup> floor hose reel drum found removed.
3. Fire pump of 450 lpm capacity found non-functional.
4. Overhead water storage tank found domestic connection. Overhead water storage tank are delicately metered for fire fighting.
5. Standby power supply found removed.
6. Exit signages found removed.
7. Smoke management system is not provided in upper floors.
8. Lift grounding switch found non-functional.

In view of the above shortcomings, the application for renewal of Fire Safety Certificate cannot be considered at this stage & rejected. The occupancy of the building/premises in absence of requisite fire safety arrangements shall be at the risk and liability of the owner/occupier.

Yours faithfully,

(Atul Garg)  
Director

06/07/23