

## GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELIII HEADQUARTERS: DELHI FIRE SERVICE: NEW DELHI- 110001

No.F6/DFS/MS/School/SZ/2023/367

Dated:

13-07-202

To

The Principal, Divine Shine Public School, 553, Bank Colony Bandh Road, Near Muthoot Fincrop, Sangam Vihar, New Delhi-80.

Regarding issuance of Fire Safety Certificate in respect of M/s Divine Shine Public School Sub:located at 553, Bank Colony Bandh Road, Near Muthoot Fincrop, Sangam Vihar, New Delhi-80.

Sir,

With reference to your letter no. nil dated 09.03.2023 on the subject cited above, it is informed that the school building was inspected by Assistant Divisional Officer (M. Road) from this department on 10.07.2023 in the presence of Mr. Dev Kumar (Owner) and it was observed that the school is running on Basement + Ground + 1 upper floor of the building which is comprised of Basement + Ground + 2 upper floors. During the inspection following shortcomings were observed:-

1. Teaching activities are not permitted in the basement.

- 2. Automatic Sprinkler System found not provided in basement area more than 200 m<sup>2</sup>.
- 3. Fire pump having capacity 450 LPM & head 40 m found not provided.
- 4. Overhead tank capacity of 5,000 liter found not provided for sprinkler system.

5. Exit sinages found not provided.

In view of above shortcomings, the application for issuance for Fire Safety Certificate is rejected. The occupancy of the building/premises in absence of requisite fire safety arrangements shall be at the risk and liability of the school management. The Authority/Statutory Authority may take suitable necessary action as deemed fit.

Yours faithfu

Director

Delhi Fire Service

Copy to:-.

The Dy. Director of Education, GNCT of New Delhi DISST. South Block-C, Defence Colony, New Delhi-24.