

**GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI**  
**HEADQUARTERS: DELHI FIRE SERVICE: NEW DELHI-110001**

No. F.6/DFS/MS/2023/SZ/ 1485  
To

Dated: 18/07/2023

Mr. Ratan Roy,  
Estate Manager  
98 Hemkunt Tower Upkeep Society,  
New Delhi 110019

Sub: Regarding issuance of Fire Safety Certificate in r/o Building 98, Hemkunt Tower UPKEEP Society, New Delhi 110019.

Sir,

This has reference with your letter received through outdoor diary no 3260 dated 30/06/2023 & 1787 dated 09/05/2023 on the subject cited above. In this connection, it is to inform you that the inspection of above said building have been carried out by the officer concerned of this department on 10/07/2023 in the presence of Mr. Brijesh Kumar and observed to verify the fire safety measures installed in the building. During inspection, following points were observed:

1. The Fire Check door found removed at some places.
2. Smoke ventilation system provided but found nonfunctional.
3. First aid hose reel provided but found nonfunctional.
4. Automatic detection system provided but found nonfunctional.
5. MOEFA not provided.
6. Public address system found removed.
7. Automatic sprinkler system provided but found nonfunctional.
8. Internal hydrant provided but found nonfunctional.
9. Fire fighting pumps are provided but found nonfunctional.
10. Exit signage found removed.

In view of above Shortcomings, the application for issuance Fire Safety Certificate is rejected. The occupancy of the building/premises in absence of requisite fire safety arrangements shall be at the risk and liability of the owner/occupier.

Yours faithfully,

(ATUL GARG)  
DIRECTOR

DELHI FIRE SERVICE

o/m