

GOVERNMENT OF NATIONAL CAPITAL TERRITOTY OF DELHI **HEADQUARTERS: DELHI FIRE SERVICE: NEW DELHI- 110001**

No. F6/DFS/MS/School/2023/SZ/ 303

Dated: 01/08 /2023

To

The Executive Engineer (Bldg) HQ, 9th floor, Civic Center, Minto Road, New Delhi 110002.

Sub: - Regarding issuance of Fire Safety Certificate in r/o Amrita Vidyalayam, Sec-7, Pushp Vihar, M.B. Road, New Delhi-110017.

Sir,

This has reference to with Online ID 10063121 dated 25/07/2023 on the subject above. In this connection, this is to inform you that joint inspection of the premise was conducted by the team of officers from Delhi Fire Service on 27/07/2023 in the presence of Mr. Honey Aggarwal (JE/Bldg/MCD) to check the compliance of fire safety arrangements from fire safety point of view and following shortcomings were observed:

- 1. The Road widths of all around the building at two sides are less than of 06 mtr wide.
- 2. The width of all staircases are 1.40 mtr wide against the required width of 1.50 mtr each.
- 3. Fire check doors not provided at staircase as marked on building plan.

4. Exit Signage not provided.

In view of above Shortcomings, the application for issuance Fire Safety Certificate is rejected. The occupancy of the building/premises in absence of requisite fire safety arrangements shall be at the risk and liability of the owner/occupier. The Licensing authority/ Statutory Authority may take suitable necessary action as deemed fit.