GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUATERS: DELHI FIRE SERVICE: NEW DELHI-110001

No: F.6/DFS/MS/School/SZ/2023/309

ELHI-110001 Dated: - 0月10812023

To.

The Principal, Sunhill Public School, 2756, Ranjeet Nagar (South Patel Nagar), New Delhi- 110008.

Sub.:- Regarding issued of Fire Safety Certificate in r/o Sunhill Public School, 2756, Ranjeet Nagar (South Patel Nagar), New Delhi- 110008.

Sir.

Please refer to your letter No. SPS/567/2023 dated 13.07.2023, on the subject cited above. In this connection, it is to inform you that the aforesaid school building have been inspected by the officer concerned of this department in presence of Smt. Shalina, Principal of the School on 26.07.2023 to check the functionability of the existing fire safety arrangements in the school building.

During the inspection, it has been observed that the said school building comprised of ground plus two upper floors, said school building served by two nos. of staircases from ground to terrace. Fire safety arrangements such as fire extinguishers, D.G. Set etc. found provided in the school building. However, the following shortcomings were observed:-

1. Main gate having width 2.05 mts. against requirement of 4.50 mts.

- 2. Found two staircase having width 0.98 & 0.94 mts. against requirement of two staircase width of 1.50 mts each.
- 3. Door size found 0.95 mts against requirement width of 1.20 mts.
- 4. First aid hose reel found not provided.
- 5. MOEFA found not provided.
- 6. Terrace pump found not provided
- 7. Overhead water storage tank found not provided.
- 8. Exit singes found not provided at some places.

In view of the above shortcomings, 'Fire Safety Certificate' cannot be issued at this stage. You are requested to rectify the above-mentioned shortcomings under intimation to this department.

Yours faithfully

ul Garg)

Delhi Fire Service

Copy to: -

The Director of Education, Govt. of NCT of Delhi, Old Secretariat, New Delhi-110054. for information please.