

## GOVERNMENT OF NATIONAL CAPITAL TERRITOTY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: CONNAUGHT PLACE **NEW DELHI- 110001**

F.6/DFS/MS/School/2023/SZ/ 37-6 No.

Dated: 04/09./2023

To

The Principal, Baba Banda Singh Bahadur Memorial Secondary School, Mehrauli, New Delhi 110030

Regarding issuance of FSC in r/o Baba Banda Singh Bahadur Memorial Secondary School, Sub: Mehrauli, New Delhi 110030.

Sir,

This has reference to letter no. BBSB/August/2023/1234 dated 19/08/2023 on the subject cited above. In this connection, this is to inform you that the above mentioned premise was visited by the officer concerned of this department on 24.08.2023 to verify the fire safety measures installed in the building. Accordingly fire safety arrangement were tested / checked and found following observation.

- 1. Additional staircase required in both block with clear width of not less than 0.75m.
- 2. Fire/Smoke check door is not provided at basement floor.
- 3. Smoke management system is not provided at basement floor.
- 4. 03 nos of fire extinguisher are provided against the required 16 nos. of fire extinguisher.
- 5. First aid hose reel are not provided at each floor.
- 6. Boosting arrangement (A Pump having discharge capacity of 450 LPM and 40m Head) for hose reel is not provided.
- 7. Overhead water tank capacity of 10,000 ltrs for firefighting is not provided at terrace level.
- 8. Exit signage not provided at conspicuous place at every floor.

The same observation has already been issued and communicated earlier by this department vide letter of even no 503 dated 13.05.2020.

In view of above Shortcomings, the application for issuance Fire Safety Certificate is rejected. The occupancy of the building/premises in absence of requisite fire safety arrangements shall be at the risk and liability of the owner/occupier.

DELHI PIRE'

Copy to:-

1. The Director of Education, Govt. of NCT of Delhi, Old Secretariat, New Delhi 110054.