

C-45

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEADQUARTERS: DELHI FIRE SERVICE, NEW DELHI-110001

No: F.6/DFS/MS/School/2023/SZ/ 385

Dated: 06/09/2023

To,

The Principal,
Kendriya Vidyalaya Vikaspuri, Hastal Village,
Uttam Nagar, New Delhi-110059.

Sub: - Regarding renewal of Fire Safety Certificate in r/o. Kendriya Vidyalaya, Vikaspuri,
Hastal Village, Uttam Nagar, New Delhi-110059.

Sir,

Please refer to your letter No. KVVP/14511018/123 dated 16/08/2023 on the subject cited above. In this connection, it is to inform you that the inspection of above said school building has been carried out by officer concerned of this department on 28/08/2023 to see the compliance of the requisite fire safety measures. Smt. Poonam Jain (Principal) was present at the time of inspection and it was observed that the school building is comprised of ground plus three upper floors and have following shortcomings:-

1. Fire extinguishers are provided but not functional.
2. Hose reel system provided but not functional.
3. Fire pumps of 450 LPM capacity provided but not functional.
4. Over head water storage tank found damage.
5. Exit signs were found missing at various places.

In view of above, the school building cannot be considered for grant of fire safety certificate at this stage. Therefore you are suggested to rectify the above said shortcomings under the intimation to this department for further course of action.

Yours Faithfully,


(Anil Garg)
Director
Delhi Fire Service
9/9/23

Copy to:-

The Dy. Commissioner,
K.V.S, Delhi Region, JNU Campus,
New Mehrauli Road, New Delhi-110067

(for taking necessary action as school does not have valid fire NOC/FSC)