

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEADQUARTERS: DELHI FIRE SERVICE: NEW DELHI-110001

No. F.6/DFS/MS/2023/SZ/ 3033
To

Dated: 06/10/2023

Mr. Ratan Roy,
Estate Manager
98 Hemkunt Tower Upkeep Society,
New Delhi 110019

Sub: Regarding issuance of Fire Safety Certificate in r/o Building 98, Hemkunt Tower UPKEEP Society, New Delhi 110019.

Sir,

This has reference with your Email dated 27/07/2023 on the subject cited above. In this connection, it is to inform you that the inspection of above said building have been carried out by the officer concerned of this department on 29/09/2023 in the presence of Mr. R. Roy (Estate Officer) and observed to verify the fire safety measures installed in the building. During inspection, following points were observed:

1. The Fire Check door found removed at some places.
2. Smoke ventilation system provided but found nonfunctional.
3. First aid hose reel provided but found nonfunctional.
4. Automatic detection system provided but found nonfunctional.
5. MOEFA not provided.
6. Public address system found removed.
7. Automatic sprinkler system provided but found nonfunctional.
8. Internal hydrant provided but found nonfunctional.
9. Fire fighting pumps are provided but found nonfunctional.
10. Exit signage found removed.

In view of above Shortcomings, the application for issuance Fire Safety Certificate is rejected. The occupancy of the building/premises in absence of requisite fire safety arrangements shall be at the risk and liability of the owner/occupier.

Yours Faithfully,

(ATUL GARG)
DIRECTOR
DELHI FIRE SERVICE

of/d w