

## GOVERNMENT OF NATIONAL CAPITAL TERRITOTY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: CONNAUGHT PLACE NEW DELHI- 110001

No. F.6/DFS/MS/BNQT/2023/SZ/ 225

Dated: 25./..J.O./2023

The Deputy Health Officer, Central Zone, MCD, Jal Vihar Lajpat Nagar, New Delhi 110024.

Sub: Regarding issuance of FSC in r/o (Banquet Hal) M/s Eswara Kamdhenu Restaurant Pvt Ltd at Entire Ground Floor of Property No 59/18, R.D Marg, Kalkaji, New Delhi 110019

Sir,

This has reference to with MHA Portal ID 2023092516376 dated 25/09/2023 on the subject cited above. In this connection, this is to inform you that the above mentioned premise was visited by the officers concerned of this department on 07.10.2023 in the presence of Mr. D.N Joshi to verify the fire safety measures installed in the building. Accordingly fire safety arrangement were tested / checked and found following observation.

- 1. There are two staircase having width of 1.50 mtr each against the required width of 2m & 1.50 mtr.
- 2. There are 02 exit doors having width of 1.50m & 1.0m. The minimum widths of two exit doors are required 2m/1.50 mtr each as per UBBL-2016.
- 3. First aid hose reel not provided.
- 4. Internal hydrant not provided.
- 5. Terrace level Fire Pump capacity less than 900 LPM not provided.
- 6. Overhead tank capacity 25,000 ltrs not provided.
- 7. Exit Signage not provided.

In view of above Shortcomings, the application for issuance Fire Safety Certificate is rejected. The occupancy of the building/premises in absence of requisite fire safety arrangements shall be at the risk and liability of the owner/occupier. The Licensing authority/ Statutory Authority may take suitable necessary action as deemed fit.

DIRECTOR
LHI FIRE SERVICE