

**GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI**  
**HEADQUARTERS: DELHI FIRE SERVICE: CONNAUGHT PLACE**  
**NEW DELHI- 110001**

No. F.6/DFS/MS/GH/2023/SZ/ 549  
To

Dated: 31.10.2023

The Addl. Commissioner of Police,  
Lic/Branch, 1<sup>st</sup> Floor, P.S Defence Colony  
New Delhi 110049.

Sub: Regarding issuance of FSC in r/o M/s Shyama International located at C-5/32, Safdarjung development Area, New Delhi- 110029.

Sir,

This has reference with MHA Portal ID 2023100716930 dated 10/10/2023 on the subject cited above. In this connection, the premises have been inspected by officer concerned of this department on 25.10.2023 in the presence of Mr. Umesh Kumar of the Guest House. During the inspection, it was observed that the Guest House is running Ground plus Three Upper Floors. The shortcomings observed are as below:

1. Smoke management system not provided in the building as per clause 7.31 of UBBL-2016
2. Carbon Monoxide detector not provided as per clause 7.31 of UBBL 2016.
3. MOEFA found removed.
4. Fire Fighting pump not on auto mode.

In view of above Shortcomings, the application for issuance Fire Safety Certificate is rejected. The occupancy of the building/premises in absence of requisite fire safety arrangements shall be at the risk and liability of the owner/occupier. The Licensing authority/ Statutory Authority may take suitable necessary action as deemed fit.

Yours faithfully,

(ATUL GARG)  
DIRECTOR

DELHI FIRE SERVICE

of n ~