

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: NEW DELHI- 110001



No. F6/DFS/MS/EH/SZ/2023 632

Dated: 211112023

To

The Joint Commissioner of Police, Office of Joint commissioner of Police: Licensing, 1st Floor, P S Defence Colony, New Delhi.

Sub: - Regarding renewal of Fire Safety Certificate in r/o M/s Pind Balluchi Restaurant (A Unit of J.S. Hospitality Services Pvt. Ltd.) located at M-58, Lajpat Nagar-II, New Delhi-24. Sir.

With reference to the MHA online I.D. no. 2023102617737 dated 06.11.2023 on the subject cited above, it is informed that the said restaurant was inspected by officer concerned of this department on 15.11.2023 in the presence of Mr. Vineet, Manager and it was observed that the restaurant is running only at 2nd floors of the building which is comprised of Ground (Mercantile) + 02 upper floors. During the inspection the following shortcomings were observed:

- 1. Hose reel & down comer system found not functional.
- 2. Manual Operated Electrical Fire Alarm (MOEFA) system found not functional.
- 3. Fire pump having capacity 450 LPM shall be provided instead low capacity fire pump.
- 4. Overhead water tank of 10,000 liters shall be provided against the existing tank of 3,000 liters.
- 5. Exit signages are not adequate.
- 6. Exhaust provision must be provided in seating area.
- 7. Segregation of common staircase is required at first floor by means of fire check door (FCD).

In view of above shortcomings, the application for renewal of Fire Safety Certificate is rejected. The occupancy of the building/premises in absence of requisite fire safety arrangements shall be at the risk and liability of the management. The Authority/Statutory Authority may take suitable necessary action as deemed fit.

Yours f

Director

Delhi Fire Service

161" 22 h