

No.F6/DFS/MS/School/SZ/2023

587

Dated:

15/12/23

To

The Principal, M/s Iqra International School, H-698, Jaitpur Ext-II, New Delhi-44.

Sub: Regarding renewal of Fire Safety Certificate in respect of M/s Iqra International School, located at H-698, Jaitpur Ext-II, New Delhi-44.

Sir,

This has reference to letter bearing outdoor diary no. 2553 dated 06.06.2023 on the subject cited above. In this context it is informed that the said building was inspected by the officer concerned of this department on 01.12.2023 in the presence of Mr. Saeedur Rehman (Caretaker) and it was observed that school building is comprised of Ground + 03 upper floors. During the inspection following shortcoming were observed:-

1. Alternate staircase having width 1.70 m was found blocked between Ground & 1st floor.

2. Fire pump having capacity 220 LPM provided against the requirement of 450 LPM.

In view of above shortcomings, the application renewal of Fire Safety Certificate is rejected. The occupancy of the building/premises in absence of requisite fire safety arrangements shall be at the risk and liability of the school management. The Statutory Authority may take suitable necessary action as deemed fit.

Yours faithfully

Director

Delhi Fire Service

Copy to:-.

1. The Dy. Director of Education, GNCT of New Delhi DISST. South Block-C, Defence Colony, New Delhi-24.