

## GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: NEW DELHI- 110001



No. F6 /DFS/MS/Industrial/SZ/2023 / 41

Dated: 18 12 2023

To,

The Owner/occupier,
Pitamber Steels (P) ltd.,
Plot no. B-2/2, MCIE, Mathura Road, New Delhi

Sub: - Regarding renewal of Fire Safety Certificate in r/o Pitamber Steels (P) ltd., located at Plot no. B-2/2, MCIE, Mathura Road, New Delhi.

Sir,

With reference to the your letter no. nil dated 20.11.2023 on the subject cited above, it is informed that the said building was inspected by a team of officers concerned of this department on 07.12.2023 in the presence of Mr. Yogesh (Owner representative) and it was observed that the building is comprised of Basements + Ground + 02 upper floors. During the inspection following shortcomings were observed:

- 1. Fire check door (FCD) found removed.
- 2. Vertical & horizontal opening found not sealed.
- 3. No ventilation provision in basement.
- 4. Fire pump found not in auto mode.
- 5. Underground water tank found empty.

In view of above shortcomings, the application for issuance for Fire Safety Certificate is rejected. The occupancy of the building/premises in absence of requisite fire safety arrangements shall be at the risk and liability of the management. The Authority/Statutory Authority may take suitable necessary action as deemed fit.

(Attl Garg)

Director
Delhi Fire Service

Yours fa

Copy to:-.

1. The Executive Engineer (Building), South DMC, Jal Vihar, Lajpat Nagar, New Delhi-24.