

## GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELIII HEADQUARTERS: DELIII FIRE SERVICE: NEW DELIII- 110001



No.F6/DFS/MS/School/SZ/2023/ 604

Dated: 22-12-2023

To

The Principal, M/s Bal Vidya Mandir Public School, 435/4, Lakhpat Colony Part-II, Mithapur Extension, Badarpur, New Delhi-44.

Sub:- Regarding issuance of Fire Safety Certificate in respect of M/s Bal Vidya Mandir Public School located at 435/4, Lakhpat Colony Part-II, Mithapur Extension, Badarpur, New Delhi-44.

Sir,

With reference to your letter no. BVMPS/07/2023 dated 27.07.2023 on the subject cited above, it is informed that the school building was inspected by Assistant Divisional Officer (M. Road) from this department on 18.12.2023 in the presence of Mrs. Jyoti Sharma (Principal) and it was observed that the building is comprised of Ground + 1 upper floor. During the inspection following shortcomings were observed:-

- 1. Six nos. of Fire Extinguishers found not provided.
- 2. Alternate exit (Iron staircase) should not be approachable through the occupied area /any class room.
- 3. Exit sinages found not provided.

In view of above shortcomings, the application for issuance for Fire Safety Certificate is rejected. The occupancy of the building/premises in absence of requisite fire safety arrangements shall be at the risk and liability of the school management. The Authority/Statutory Authority may take suitable necessary action as deemed fit.

(Autoria)

Director

Delhi Fire Service

Copy to:-.

1. The Directorate of Education, Center Zone: Lajpat Nagar, New Delhi-110024.