## GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELIII HEADQUARTERS: DELIII FIRE SERVICE: NEW DELIII- 110001



No. F6 /DFS/MS/Industrial/SZ/2024 40

Dated: 08 01 2021

To,

The Owner/occupier/manager, M/s Plot No. B-II/68, MCIE, Mathura Road, New Delhi-44.

Sub: - Regarding renewal of Fire Safety Certificate in r/o M/s Building located at Plot No. B-II/68, MCIE, Mathura Road, New Delhi-44.

Sir,

With reference to the your Email dated 29.12.2023 on the subject cited above, it is informed that the said building was inspected by a team of officers concerned of this department on 03.01.2024 in the presence of Mr. Pawan (Representative) and it was observed that the building is comprised of Basements + Ground + 02 upper floors. During the inspection following shortcomings were observed:

- Fire check door (FCD) & Pressurization system found removed.
- 2. Vertical & Horizontal opening found not sealed.
- 3. Ventilation in basement and upper floors found not provided.
- One hose reel found removed.
- 5. Automatic Fire Detection and Alarm System (ADAS) found removed.
- 6. Manual Operated Electrical Fire Alarm (MOEFA) system found non functional.
- 7. Sprinkler system is in bad state of maintenance and some areas are not covered.
- 8. Hydrant system not provided at terrace level.
- 9. DG fire pump found removed.
- 10. Overhead tank of 20,000 liters capacity found not provided.
- 11. Pressurization of lift shaft & lift lobby found not provided.

In view of above shortcomings, the application for issuance for Fire Safety Certificate is rejected. The occupancy of the building/premises in absence of requisite fire safety arrangements shall be at the risk and liability of the management. The Authority/Statutory Authority may take suitable necessary action as deemed fit.

Yours faithfull

Director

Delhi Fire Service

Copy to:-.

1. The Executive Engineer (Building), South DMC, Jal Vihar, Lajpat Nagar, New Delhi-24.