

## GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: NEW DELHI- 110001



No. F6 /DFS/MS/C.C/NDZ/2024/28

Dated: 17/01/2024

Mr. Abhinav Jain (Manager), BYJU"S Tuition Centre, Property No. 2<sup>nd</sup> floors, 26 Block F, Preet Vihar, Delhi-110092.

Sub: - Regarding grant of Fire Safety Certificate in r/o BYJU"S Tuition Centre, Property No. 2<sup>nd</sup> floors, 26 Block F, Preet Vihar, Delhi-110092.

Sir,

This has a reference to your outdoor dairy no. 5096 dated 18/08/2023, on the subject cited above. In this connection, it is to inform you that premises was inspected by the officers concerned of this department on 05/01/2024 in the presence of Mr. Abhinav Jain (Manager) and observed that building comprised of Basement, Still (Parking) plus Upper Ground plus two upper floors. (Tuition centre is running 2<sup>nd</sup> floors only).

## Following shortcomings were observed during time of inspection:

- A single staircase of 1.40 meter width is provided against the requirement of two staircase of width 1.50 meter each.
- 2. There is only one Entry/ Exit in the centre against the requirement of two.
- 3. First-Aid-Hose Reel provided but not functional.
- 4. MOFA not provided but not functional.
- 5. Internal Hydrants Down-comer provided but not functional.
- 6. Fire pump of 450 LPM provided but not functional.
- 7. Overhead tank of 5,000 liters capacity is provided against the requirement of 20,000 liters.
- 8. Exit Signage's not provided.

In view of above shortcomings, the application for issuance for Fire Safety Certificate is rejected. The occupancy of the building/premises in absence of requisite fire safety arrangements shall be at the risk and liability of the management. The Authority/Statutory Authority may take suitable necessary action as deemed fit.

Yours faithfully

DIRECTOR

DELHI FIRE SERVICE

OC W