




GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEADQUARTERS: DELHI FIRE SERVICE, NEW DELHI-110001

c-63



No. F6/DFS/MS/WZ/2024/ 173
To,

Dated: 23/02/2024

Sh. Arun Mitter,
M/s MGF Market, Shalimar Place,
Plot No. 1, District Centre,
Shalimar Bagh, New Delhi.

Sub: - Inspection report in r/o M/s. MGF Market, Shalimar Place, Plot No. 1, District Centre, Shalimar Bagh, New Delhi.

Sir,

This has reference to your e mail id dated 30/01/2024 on the subject cited above. In this connection, it is to inform you that the inspection of above said building has been carried out by officer concerned of this department on 20.02.2024 to see the compliance of the requisite fire safety measures. Sh. Yogesh Kumar was present at the time of inspection.

During the course of inspection it was observed that the building comprised of Basement, Ground & Two upper floors. Your request for renewal of FSC is rejected as the following shortcomings were observed:

1. Fire check door found broken.
2. Door width found reduced to 1.10 m at some places against the required width of 1.5 m.
3. Smoke ventilation system in basement found provided but not functional.
4. Detectors found removed at some places.
5. Sprinklers found removed at some places.
6. Exit signage's found removed at some places.
7. Pressurisation of lift lobby found provided but not functional.

In view of the above shortcomings, the application for renewal of Fire Safety Certificate is not considered at this stage & rejected. The occupancy of the Building/ premises in absence of requisites fire safety arrangements shall be at the risk and liabilities of the Owner/ Occupier.

Yours faithfully,

(Atul Singh)
Director

Copy to:-

1. Sh. Arun Mitter, MGF Market, Shalimar Place, Plot No. 1, District Centre, Shalimar Bagh, Delhi.