

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEADQUARTERS: DELHI FIRE SERVICE, NEW DELHI-110001



No. F6/DFS/MS/WZ/2024/HTZ/10
 To,

Dated: 29/02/2024

Sh. Ghanshyam Bhardwaj,
 M/s Brilliant Build Tech Pvt. Ltd.,
 District Centre, Shalimar Bagh, Delhi-110088.

Sub: - Inspection report in r/o M/s. Brilliant Build Tech Pvt. Ltd., District Centre, Shalimar Bagh, Delhi-110088

Sir,

This has reference to your application received via form J received through outdoor diary number 11917 dated 15/01/2024 on the subject cited above. In this connection, it is to inform you that the inspection of above said building has been carried out by officer concerned of this department on 20.02.2024 to see the compliance of the requisite fire safety measures. Sh. Ghanshyam Bhardwaj was present at the time of inspection.

During the course of inspection it was observed that the building comprised of 03 tier Basement, Ground plus 10 upper floors. Your request for renewal of FSC is rejected as the following shortcomings were observed:

1. Fire check doors found removed at some places.
2. Smoke ventilation system in basement not found in automation and provided but not functional in banquet hall.
3. Detectors found removed at some places.
4. Sprinklers found removed at some places.
5. Pumping system not found in automation.
6. Exit signage's found removed at some places.
7. Pressurisation of lift lobby found removed.
8. Temporary structure at 2nd floor (above banquet hall) shall be removed.
9. Co2 flooding system not provided near HT & LT Panel in basement.

In view of the above shortcomings, the application for renewal of Fire Safety Certificate is not considered at this stage & rejected. The occupancy of the Building/ premises in absence of requisites fire safety arrangements shall be at the risk and liabilities of the Owner/ Occupier.

Yours faithfully,


 (Atul Garg)
 Director

Copy to:-

1. Sh. Ghanshyam Bhardwaj, M/s Brilliant Build Tech. Pvt. Ltd., District Centre, Shalimar Bagh, Delhi- 110088.