GOVERNMENT OF NATIONAL CAPITAL TERRITOTY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: CONNAUGHT PLACE NEW DELHI- 110001

F.6/DFS/MS/GH/2024/SZ/96 No. To

Dated: 19.103.12024

The Addl. Commissioner of Police, Lic/Unit, 1st Floor, P.S Defence Colony New Delhi 110049.

Sub: Regarding issuance of FSC in r/o M/s Bloom Boutique (A Unit of Imperative Hospitality Pvt. Ltd.) C-10, M Block Market, Greater Kailash Part -1, Delhi 110048 Sir.

This is in reference with MHA Portal ID 2024022602160 dated 26/02/2024 on the subject cited above. In this connection, the premises have been inspected by officer concerned of this department on 08.03.2024 in the presence of Mr. Anup (Manager) of the Guest House. During the inspection, it was observed that the Guest House is running Ground + Three Upper Floors. The shortcomings observed are as below:

1. Smoke management system not provided as per clause 7.31 of UBBL 2016.

Carbon Monoxide detector not provided as per clause 7.31 of UBBL 2016.

3. Fire fighting pumps are not on auto mode.

4. The Exit Signage found removed at some places.

In view of above Shortcomings, the application for issuance Fire Safety Certificate is rejected. The occupancy of the building/premises in absence of requisite fire safety arrangements shall be at the risk and liability of the owner/occupier. The Licensing authority/ Statutory Authority may take suitable necessary action as deemed fit.

RE SERVICE

Yours faithf