

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEADQUARTERS: DELHI FIRE SERVICE: CONNAUGHT PLACE
NEW DELHI - 110001

No.F6/DFS/MS/SZ/2024/ 184

Dated: 10/04/2024

To,

The Joint Director (Building),
DDA, Vikas Sadan,
INA, Delhi-110023

The, Executive Engineer -cum
Resident Engineer, Building Division,
Bihar Bhawan, Chanakyapuri, New Delhi-110021

Subject: - Renewal of fire safety certificate in r/o Bihar Sadan, Located at Sector-19, Pocket - 1, Dwarka, New Delhi-110075.

Sir,

Please refer to letter No-185, dated 15/03/2024 on the subject mentioned above. In this connection it is to inform you that the premise was re-inspected by the officer concerned of this department on 04/04/2024 in the presence of Sh. Amit Kumar (GM) from fire safety point of view.

During the course of inspection following shortcomings are observed

1. Fire check door found removed in basement.
2. Staircases found locked at some places.
3. The corridor found partially blocked.
4. Smoke exhaust system provided in basement found nonfunctional in auto mode.
5. Pressurization system provided in lift shafts & staircases found nonfunctional in auto mode.
6. Communication system in lift found nonfunctional.
7. Flammable material found stored below staircases at some places.

In view of the above shortcomings renewal of Fire Safety Certificate from fire safety point of view cannot be considered at this stage. You are directed to comply the shortcomings under intimation to this department for further consideration in the matter.

Yours faithfully,

(Atul Garg)
Director
Delhi Fire Service

ok

Copy to:-

The Manager, Bihar Sadan, Located at Sector-19, Pocket - 1, Dwarka, New Delhi-110075.