

**GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI  
HEADQUARTERS: DELHI FIRE SERVICE: NEW DELHI-110001**

No. F.6/DFS/MS/EH/2024/SZ 141  
To

Dated: 19/04/2024

The Addl. Commissioner of Police,  
Lic Branch, 1<sup>st</sup> Floor, PS Defence Colony,  
New Delhi 110049.

Sub: Regarding issuance of Fire Safety Certificate in r/o M/s ISKCON located at ISKCON temples complex, Hare Krishna Hills Sant Nagar, East of Kailash, New Delhi 110065

Sir,

This is in reference to with **MHA Portal ID 2024022302066 dated 29/03/2024** on the subject cited above. In this connection, this is to inform you that the above mentioned premise was visited by the officer concerned of this department on 08.04.2024 to verify the fire safety measures installed in the building and observed that the restaurant is running at Ground floor. Accordingly fire safety arrangement were tested / checked and found following observation.

1. First Aid Hose reel hose provided but found non-functional.
2. MOEFA found not working.
3. Terrace level Fire Pump capacity of 225 LPM provided but found non-functional.
4. Exit signage found removed at some places.

In view of above Shortcomings, the application for issuance Fire Safety Certificate is rejected. The occupancy of the building/premises in absence of requisite fire safety arrangements shall be at the risk and liability of the owner/occupier. The Licensing authority/ Statutory Authority may take suitable necessary action as deemed fit.

Yours faithfully

(ATUL GARG)  
DIRECTOR  
DELHI FIRE SERVICE