



GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI **HEADQUARTERS: DELHI FIRE SERVICE, NEW DELHI-110001**

F.6/DFS/MS/Indl./2024/SZ/ 3 | L

Dated: 25 / 04 /2024

To

Sh. Bratindra Chakraborty, M/s InterGlobe Aviation Limited (IndiGo), Room No. 34, Terminal 1D, IGI Airport, New Delhi-110037

Sub: Regarding renewal of Fire Safety Certificate in r/o M/s IndiGo Aircraft Maintenace (Hanger, Support Building & Workshop) at Plot Near Peer Baba, Terminal 2, IGI Airport, New Delhi-110037

Sir,

Please refer to your letter received in this office through outdoor diary No. 13989 dated 07/03/2024, on the subject cited above. In this connection, it is to inform you that the said premises was inspected by the officers concerned of this department on 10/04/2024 from fire safety point of view in the presence Mr. Satya Prakash (AM-Admin) & Mr. Rishabh Bhardwaj (AM-Facility). During the course of inspection, the shortcomings observed are as below.

- 1. The smoke management/ventilation system in support building found non-functional.
- 2. The hose-reel hose found removed in workshop block.
- 3. Automatic Sprinkler System need to be extended in left over area/wheel store
- Exit signage provided found inadequate & faded at some places.

In view of the above, the application for renewal of Fire Safety Certificate is rejected. The occupancy of the building/premises in the absence of requisite fire safety arrangements shall be at the risk and liability of the owner/occupier.

Yours faithfully,

DELHI FIRE SERVICE

DIL 82

Copy to: -

1. The Chief Executive Officer, DIAL, New Udaan Bhawan, Opp. Terminal - 3, IGI Airport, New Delhi-110037