



GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEADQUARTERS: DELHI FIRE SERVICE, NEW DELHI-110001



No. F6/DFS/MS/WZ/2024/ 244
To,

Dated: 08/05/2024

Sh. Sunil K Jain,
Aggarwal Corporate Height,
A-7, Netaji Subhash Place,
Pitampura, Delhi-110034.

Sub: - Inspection report in r/o M/s. Aggarwal Corporate Height located at A-7, Netaji Subhash Place, Pitampura, Delhi- 110034.

Sir,

Please refer to your letter no. nil dated 15/02/2024 received through outdoor diary no. 13164 dated 15/02/2024 on the subject cited above. In this connection, it is to inform you that the above said building was re-inspected by the officers concerned by this department on 02/05/2024 in the presence of Sh. Ajay Chauhan to see the compliance of shortcomings communicated vide this department letter No.F6/DFS/MS/WZ/2023/2075 dated 27/09/2023.

During the course of inspection following shortcoming has been observed and status is as under:-

Sr. No	Shortcomings	Status
1.	Fire Check Doors found replaced with normal doors.	Not Rectified
2.	Detection system found removed at some floors & found non functional at some floors.	Rectified
3.	Detection system of some floors found not integrated to the main panel of the building.	Not Rectified
4.	Ventilation system of common corridor found removed at some floors.	Not Rectified
5.	At 10 th floor exit door width found reduced to its actual width.	Rectified
6.	Exit signage's found removed at some places.	Rectified

In view of the above shortcomings, the application for renewal of Fire Safety Certificate is not considered at this stage & rejected. The occupancy of the Building/ premises in absence of requisites fire safety arrangements shall be at the risk and liabilities of the Owner/ Occupier.

Yours faithfully,

(Atul Garg)
Director

Delhi Fire Service

Atul Garg