

**GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI**  
**HEADQUARTERS: DELHI FIRE SERVICE, NEW DELHI-110001**

No. F6/DFS/MS/WZ/2024/233  
To,

Dated: 10/05/2024

The Executive Engineer (E),  
PWD Edu. Elect. Div. M 1 (N),  
ITI Campus, Pusa, New Delhi- 110012.

**Sub: - Inspection report in r/o New Block at Govt. Girls Sr. Sec. School, Rani Bagh, Delhi, 110034.**

Sir,

This is in reference to your e-mail id dated 23/04/2024 on the subject cited above. In this connection, it is to inform you that the above said building was re-inspected by the officer concerned of this department on 08/05/2024 in the presence of Smt. Sunita Sharma (Principal) to verify the compliance of shortcomings communicated vide this department letter No. F6/DFS/MS/School/WZ/2023/246 dated 15/05/2023.

The status of shortcoming is as under:-

Sr. No	Shortcomings	Status
1.	Width of exits in M.P. hall is less than required width of 2 m each.	Not Rectified

In view of the above shortcomings, the request for issuance of Fire Safety Certificate can not be considered at this stage & rejected. You are advised to rectify the above mentioned shortcoming under intimation to this department for further necessary action in this regard.

Yours faithfully,

  
(Atul Garg)  
Director

Ph. 011-23414000

Copy to:-

1. The Executive Engineer, Education North West Division, PWD, Dr. BSA Hospital, Sec. 6, Rohini, Delhi-110085.
2. The Principal, Govt. Girls Sr. Sec. School, Rani Bagh, Delhi- 110054.