

GOVERNMENT OF NATIONAL CAPITAL TERRITOTY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: NEW DELHI- 110001

No. F6/DFS/MS/School/2024/SZ/ 219

Dated: 08/05 /2024

The Executive Engineer (Bldg) HQ, 9th floor, Civic Center, Minto Road, New Delhi 110002.

Sub: - Regarding issuance of Fire Safety Certificate in r/o Amrita Vidyalayam, Sec-7, Pushp Vihar, M.B. Road, New Delhi-110017.

Sir,

This has reference to with **Online ID 10063121 dated 30/04/2024** on the subject above. In this connection, this is to inform you that joint inspection of the premise was conducted by the team of officers from Delhi Fire Service on 02/04/2024 in the presence of Mr. Honey Aggarwal (JE/Bldg/MCD) to check the compliance of fire safety arrangements from fire safety point of view and following shortcomings were observed:

- 1. The Road width for fire tender movement at one side is less than of 06 mtr.
- 2. The widths of staircases are between 1.40 mtr to 1.45 mtr wide against the required width of 1.50 mtr each.
- 3. Fire check doors not provided at staircase as marked on building plan. The width of exit of fire doors shall not be less than of 1.50 mtr as per UBBL 2016.
- 4. MOEFA not working.
- 5. Automatic sprinkler system at 4th floor not provided.
- Overhead water storage tank for fire fighting is having capacity of 10,000 ltrs against the requirement of 25,000 ltrs.
- 7. Exit Signage not provided.

In view of above Shortcomings, the application for issuance Fire Safety Certificate is rejected. The occupancy of the building/premises in absence of requisite fire safety arrangements shall be at the risk and liability of the owner/occupier.

Yoursifaithfully

ATUL GARG)
DIRECTOR

DELHI FIRE SERVICE